## DAMAGE ASSESSMENT IN RAKHINE STATE,

cnes


## **MYANMAR**

As Observed by Pleiades Satellite on 17 May 2023





This map shows the detected damaged buildings in Urban Village, Pauktaw Town, Sittwe Districts, Rakhine State, Myanmar, on May 17, 2023, due to heavy rains and strong winds on May 14, 2023, from Cyclone Mocha.



Satellite Image:

Pre-disaster : Pleiades on 10 Nov 2022, Post-disaster : Pleiades on 17 May 2023.

Copyright: "Pleiades © CNES (2023), Distribution Airbus DS"

GIS Data:

Road © OSM (2023) Administrative Boundary © Myanmar Information Management Unit (2023)

Map Scale 1:12,000 Coordinate System: GCS WGS 84 Datum: D WGS 84 Unit: Degree

0 0.12 0.23 0.47 0.7 0.94 Kilometers

Map product made by GIC-AIT (v1.0).

Disclaimer: The accuracy of this product is not validated.

